
Smoke and Dye Testing Summary

High Level Sewershed

Run Summary ————————————————————————————————————									
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length		
S1028-076	Smoke	9/10/2008	ADS/TM	S13AA1007MH	Dry	Yes	749.61		



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary —									
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length		
S1028-076	Smoke	9/10/2008	ADS/TM	S13AA1007MH	Dry	Yes	749.61		

ated Pipes ——				
Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S13AA1010G1	S13AA1010MH	S13CC1017MH	129.0491	8
S13AA1007G1	S13AA1007MH	S13AA1010MH	320.2027	8
S15AA1015G2	S15AA1015MH	S13AA1007MH	122.2294	8
S15AA1015G1	S15AA1015MH	S13AA1026MH	133.9971	8
S15AA1044G1	S15AA1044DE	S15AA1015MH	44.12919	8

Observations & Photos

Obs_ID S1028-076-OB01 **Address** 2812 Violet Ave

StatusPrivateSourceCleanout

Location Yard - back **Nearest MH** S13AA1026MH

Comments Smoke from cleanout in back yard. 2812 Violet

Ave.

Picture \S1028-076-OB01-P01.jpg

Comments Back of house, 2812 Violet Ave.

Obs_ID S1028-076-OB02 **Address** 3700 Reisterstown Rd

Status Private **Source** Cleanout

Location Yard - back **Nearest MH** S15AA1015MH

Comments Smoke from cleanout in back yard. 3700

Reisterstown Rd.



Picture \S1028-076-OB02-P01.jpg

Comments Back of house, 3700

Reisterstown Rd.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Run Summary									
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length		
S1028-076	Smoke	9/10/2008	ADS/TM	S13AA1007MH	Dry	Yes	749.61	_	

 Obs_ID
 \$1028-076-OB03

 Address
 3710 Reisterstown Rd

Status Private **Source** Cleanout

Location Yard - back **Nearest MH** S13AA1007MH

Comments Smoke from cleanout in back yard. 3710

Reisterstown Rd.



Picture \S1028-076-OB03-P01.jpg

Comments Back of house, 3710

Reisterstown Rd.

Obs_ID S1028-076-OB04

Address 3712 Reisterstown Rd

Status Private
Source Cleanout

Location Yard - back **Nearest MH** S13AA1007MH

Comments Smoke from cleanout in back yard. 3712

Reisterstown Rd.



Picture \S1028-076-OB04-P01.jpg

Comments Back of house, 3712

Reisterstown Rd.